



## Devil's Slide/Hwy 1 Storm Repair

Daily Updates from Bijan Sartipi



**Daily Update**  
July 17

### Repair Work

Devil's Slide (post mile 39.14)

- Level 'B' (lower level ocean side) – Tie back stressing is now complete for this level.
- Level 'D' (upper level cliff side) – Tie back installation now complete at this level. 33 of 33 now installed. Cable stressing continued. Work started to remove the temporary bench.



Stressing cables at level D



Removing the temporary bench

### Retaining (micropile) Wall

- Drilling and driving steel piles was completed today. Due to interference with a drainage pipe, one micro pile was omitted for a total of 98 installed. A concrete cap will now be cast over the tops of the micropiles.



Micropiles with drain backfilling work in the background

## Rock Bolts Above The Road

- Rock bolt drilling is now complete.

## Surface drains

- Surface drain work continued today.



Trenching for drainage pipe under the road bed

## Signs

- A 'No Right Turn on Red' is now installed at the junction of Highways 35 and 92. The temporary restriction is in effect Monday to Friday, 4 PM to 7 PM. This measure was implemented in response to congestion during the evening commute west to Half Moon Bay. Bicycle detour signs now installed at various locations. See examples below.

